

230 Vac - 3 phase
voltage supply

Pe

L1

L2

L3

fuses*



⏏



-DC




L1/L



L2/N



L3



+



BR



U



V



W



M